Reactive Red 6BX

C.I. Reactive Red 76

Light : 4

Washing : 3

Washing (Stain) : 3

Perspiration : 4

Substantivity : Medium

Dischargeability : Poor

Hypochlorite : -

Solubility at 60°C : 80 g/l

1% Cotton Dyeing 4% Cotton Dyeing 1% Cotton Printing 4% Cotton Printing .

Reactive Red H8B C.I. Reactive Red 31

Light : 4-5
Washing : 4-5
Washing (Stain) : 5

Perspiration : 3-4

Substantivity : High
Dischargeability : Poor

Hypochlorite : 3-4

Solubility at 60°C : 80 g/l

1% Cotton Dyeing

4% Cotton Dyeing

1% Cotton Printing

4% Cotton Printing

